











District Long Range Planning

Board of Education

Raytown District Building Work Session Results

October 22, 2018





Agenda

- Northwood and Herndon Dot Democracy
- RSA and District
 Building Assessment

 Review
- Bond Option #1
 Green / Yellow / Red





Sharing Ideas, Values and Vision


CAC & BOE Combined Priority Highlights

Students, Community Members, Teachers, Staff, Administrators, & Board Members



Northwood School

Priorities Highlighted



Top Priority Summary

- Roof Restoration
- 2) Interior Lighting
- 3) Classroom Outlets
- ADA Accessible Playground Equipment
- 5) Cafeteria Improvements
- Tuckpointing
- Classroom Door Replacement
- Gym Addition
- Changing Tables in rooms
- Lockable Storage in rooms
- Life Skills Room Improvements






we design the future



Herndon – Building A Priorities Highlighted



hollis _ miller

- 1) Attendance Office Window
- Floor Replacement Comitology
-) Additional Outlets in Classrooms
- 4) Bathrooms in each shop
- 5) Washer / Dryer for Cosmitology
- Main entry gutter repair
- Roof Improvements
- Breezeway lighting
- Interior Painting
- Carpet at Office





Herndon – Building B **Priorities Highlighted**

Tackboard Replacements





CULINARY CLASSROOM

hollis _ miller





AUTOMOTIVE





Exhaust ventilation leaks from Collision into Culinary

PRIORITIES

- Roof Restoration
- HVAC Diesel, Collision and Culinary
- Kitchen Hood
- Ventilation between Collision and Culinary
- **Tuckpointing**
- Classroom Door Replacement
- **Gym Addition**
- Changing Tables in rooms
- Lockable Storage in rooms
- Life Skills Room Improvements





Herndon – Building C Priorities Highlighted



LEVEL 1 CLASSROOM





NURSING



HAND WASH & FOUNTAIN



- Concrete and Parking Lot Repairs
- Covered Walkway between buildings
- 3) Window Replacement
- 4) Shower for Nursing
- 5) Hand Wash Station in Nursing
- Roof improvements
- Multi-purpose room
- Classroom casework
- Tackboard / markerboard replacement







Priorities Highlighted

EXISTING PHOTOS



MAIN ENTRY



CLASSROOM



ADA RAMP



INTERIOR DOORS



NEW A/C



SECURE ENTRY /



CORRIDOR

PRIORITIES

Additional Controlled Access to Office and Classrooms

ADA accessibility to 3rd floor

HVAC Upgrades

Cafeteria Space

Outdoor Play Equipment

Restroom Ventilation

Additional Exterior Lighting

Larger Staff Lounge

Additional Outlets in Classrooms

Library Space

Parking Lot Improvements

Street Signage for School

Update Interior Lighting Controls for dimming

RAYTOWN SUCCESS ACADEMY





- 1) Cafeteria Space
- Additional access control at Office and Classrooms
- 3) Outdoor Play Equipment
- 4) Library Space
- 5) Street Signage for School



Buildings and Grounds Priorities Highlighted

EXISTING PHOTOS PRIORITIES Restroom Improvements ADA Accessibility Improvements Tuckpointing Parking Lot / Concrete Improvements Site Drainage Interior / Exterior Lighting Upgrade, LED MAIN ENTRY BREAK ROOM RESTROOMS EXTERIOR DRAINAGE SHOP INTERIOR SHOP EXTERIOR

- **Restroom Improvements**
- **ADA Accessibility**
- **Tuckpointing**
- Parking Lot / Concrete **Improvements**
- Site Drainage
- **Lighting Upgrades**





Transportation

Priorities Highlighted

EXISTING PHOTOS PRIORITIES Concrete, Parking Lot, & Asphalt Repairs, ADA Ramp Drainage from football field causes flooding at fuel station Window Replacement - North Barn Roof Replacement - North Barn Restroom Improvements Ceiling tile replacment Casework Replacement Added Conference Room to North Barn Replace gas fired heaters at North Barn FRONT OF BUILDING Provide heating at South Barn Replace galvananized piping in South Barn Interior Lighting Upgrades at North and South Barns RESTROOMS BREAK ROOM

Top Priority Summary

- Concrete and Parking Lot Repairs
- Window Replacement North Barn
- B) Roof Replacement North Barn
- 4) Gas Fired Heaters North Barn
- 5) Add Heat South Barn



SHOP EXTERIOR



PARKING LOT

BUS BARN







Safety Center

Priorities Highlighted

EXISTING PHOTOS

FRONT OF BUILDING



PARKING LOT



GARAGE



INTERIOR STORAGE





we design the future



RESTROOM ROOF / HVAC

PRIORITIES

Drainage Updates, Building Perimeter

Site fencing in disrepair / hard to secure grounds

Tuckpointing

Window Replacements

Roof Replacement

HVAC Replacement

Exterior Door Repalcament

Flooring Improvements

Interior Doors and Hardware Replacement

Concrete, Parking Lot, & Asphalt Repairs

Interior Lighting Upgrades

Restoom Improvements

- Concrete and Parking Lot Repairs
- 2) Exterior Drainage
- 3) Tuckpointing
- 4) Window Replacement
- 5) Roof Replacement
- 6) HVAC Replacement
- 7) Restroom Improvements
- Interior and Exterior Doors and Hardware
- 9) Lighting Upgrades










Wellness Center

Priorities Highlighted



- 1) Roof Replacement
- Interior Doors
- 3) Community Meeting Room Flooring
- 4) Parking Lot / Concrete Improvements
- 5) Exercise Room Flooring
- 8) HVAC Improvements Replace RTUs







Tier 1 - Ontion 4 - 40 7M

			Her 1 - Option 4 = 40	. / 14				
Facility	BOE / CAC	Planning Criteria	Tier 1	Green	Tier 2	Yellow	Tier 3	Red
	X	Safety / Security	Guided Entry Vestibule + Attendance Office	\$262,500	Cafeteria Upgrade	\$1,181,250	*Locker Room Finish Upgrades	\$635,950
Raytown High School	X	Building Infrastructure	Windows	\$823,200	HVAC	\$630,000	*Classroom Casework	\$580,125
	X	Building Infrastructure	Roofs (HALF)	\$629,390	Façade Update	\$1,968,750		
		Building Infrastructure	Exterior Brick Tuckpointing	\$393,750				
		Building Infrastructure	Concrete & Asphalt Repairs	\$367,500				
		Enhanced Learning Environ.	Resinous Epoxy - Corridor Walls	\$0				
		Building Infrastructure	Lighting Upgrades	\$479,010				
		Enhanced Learning Environ.	Media Center Upgrade	\$350,000				
		Enhanced Learning Environ.	Gym Upgrades	\$100,000				
	X	Enhanced Learning Environ.	Interior Flooring Replacemen(Corridor Only)	\$271,405				
	X	Enhanced Learning Environ.	FACS & Band Upgrades	\$1,762,031				
	X	Enhanced Learning Environ.	Auditorium Upgrade	\$479,063				
	X	Enhanced Learning Environ.	Gym Sound System	\$32,813				
	X	Enhanced Learning Environ.	Pressbox / Locker Room Finish Upgrades	\$1,875,000	Turf Replacement	\$590,625	New Field House Construction	\$3,950,000
Chitwood Stadium	X	Building Infrastructure	ADA AcceSafety / Security	\$65,000	*Track Improvements	\$721,875		
	X	Building Infrastructure	Concrete & Asphalt Repairs	\$26,250				

hollis _ architect

Tier 1 - Option 4 = 40.7M

	X	Safety / Security	Guided Entry Vestibule	\$177,188			EFIS Façade Update	\$59,063
Raytown South High Schoo	Χ	Enhanced Learning Environ.	Gym Restroom Addition	\$472,500	Façade Update	\$1,968,750	Classroom Casework	\$669,375
	X	Enhanced Learning Environ.	Locker Room Finish Upgrades	\$498,750	HVAC	\$250,688	Auxiliary Gym Addition	\$3,780,000
	Х	Building Infrastructure	Roofs (HALF)	\$1,142,302				
	Х	Building Infrastructure	Concrete & Asphalt + (3rd Lane)	\$185,200				
	X	Enhanced Learning Environ.	Interior Flooring Replacement(Corridor Only)	\$253,125				
		Building Infrastructure	Lighting Upgrades	\$489,825				
		Building Infrastructure	Exterior Tuckpointing	\$157,500				
		Enhanced Learning Environ.	Resinous Epoxy - Corridor Walls					
	Х	Enhanced Learning Environ.	Media Center Upgrade	\$350,000				
		Enhanced Learning Environ.	Gym Upgrades	\$100,000				
	Χ	Enhanced Learning Environ.	Auditorium Upgrade	\$479,063				
	Χ	Enhanced Learning Environ.	Gym Sound System	\$32,813				
	Х	Building Infrastructure	Concrete & Asphalt Repairs	\$133,000	*Turf Replacement	\$590,625		
Raytown South Stadium								
			Tier 1 Total	\$12,388,175	Tier 2 Total	\$7,902,563	Tier 3 Total	\$9,674,513



Tier 1 - Option 4 = 40.7M

	X	Safety / Security	Guided Entry	\$511,875	Front Office Renovation	\$713,672	Classroom Casework	\$568,969
Raytown Middle School	X	Enhanced Learning Environ.	Interior Flooring Replacement(Corridor Only)	\$235,950	*Interior Painting	\$277,003		
	X	Building Infrastructure	Concrete & Asphalt Repairs	\$58,709	*Cafeteria Improvement	\$967,969		
	X	Enhanced Learning Environ.	Epoxy on Corridor Walls	\$277,003				
		Building Infrastructure	Exterior Tuckpointing	\$65,625				
		Enhanced Learning Environ.	Interior Door Replacement	\$262,500				
		Enhanced Learning Environ.	Lighting Upgrades	\$83,869				
		Building Infrastructure	Roofs	\$12,000				
		Enhanced Learning Environ.	Media Center Upgrade	\$250,000				
		Enhanced Learning Environ.	Gym Upgrades	\$100,000				
		Safety / Security	Electronic Door Access	\$56,438				
·	X	EE	Band Room Improvements	\$393,750				



Tier 1 - Option 4 = 40.7M

	X	Safety / Security	Guided Entry	\$787,500	Courtyard Improvements	\$505,313	Media Center Upgrades	\$196,875
Central Middle School	X	Building Infrastructure	Roofs (HALF)	\$578,484	Corridor Lockers	\$105,000	Classroom Casework	\$312,375
	Х	Enhanced Learning Environ.	Band Room Renovation	\$393,750			Auxiliary Gym Addition	\$2,835,000
	Х	Enhanced Learning Environ.	Interior Flooring Replacement(Corridor Only)	\$273,975				
	X	Building Infrastructure	Concrete & Asphalt Repairs	\$312,375				
	X	Enhanced Learning Environ.	Epoxy on Corridor Walls	\$183,750				
		Building Infrastructure	Exterior Tuckpointing	\$431,484				
		Enhanced Learning Environ.	Interior Door Replacement	\$126,000				
		Enhanced Learning Environ.	Lighting Upgrades	\$330,488				
	Х	Enhanced Learning Environ.	Stage Sound System Upgrades	\$32,813				
		Enhanced Learning Environ.	Media Center Upgrade	\$250,000				
	Х	Enhanced Learning Environ.	Gym Upgrades	\$100,000				
		Safety / Security	Electronic Door Access	\$56,438				
	Х	Building Infrastructure	Bus Loop Addition/Parking Lots	\$105,000				
	X	Enhanced Learning Environ.	Cafeteria Expansion	\$1,200,938				



Tier 1 - Option 4 = 40.7M

	X	Safety / Security	Guided Entry	\$175,000	Cafeteria Upgrade	\$91,875		
South Middle School	Х	Enhanced Learning Environ.	Sound System Upgrades	\$32,813	Concrete & Asphalt Repairs	\$6,038	Classroom Casework	\$500,000
	Х	Enhanced Learning Environ.	Interior Flooring Replacement(Corridor Only)	\$218,575	Media Center FF&E	\$72,844		
		Building Infrastructure	Concrete & Asphalt Repairs	\$452,025				
		Enhanced Learning Environ.	Epoxy on Corridor Walls	\$30,000				
		Building Infrastructure	Exterior Tuckpointing	\$52,500				
		Enhanced Learning Environ.	Interior Door Replacement	\$0				
		Enhanced Learning Environ.	Lighting Upgrades	\$189,000				
	Х	Enhanced Learning Environ.	Stage Sound System Upgrades	\$32,813				
	Х	Enhanced Learning Environ.	Cafeteria Flow - New entry / Exit Doors	\$60,000				
		Enhanced Learning Environ.	Media Center Upgrade	\$250,000				
		Enhanced Learning Environ.	Gym Upgrades	\$100,000				
		Safety / Security	Electronic Door Access	\$56,438				
	Х	Enhanced Learning Environ.	Band Room Upgrades	\$170,625				
		Enhanced Learning Environ.	Auditorium / Stage Upgrade	\$183,750				
	X	Building Infrastructure	Roofs (HALF)	\$466,331				
			Tier 1 Total	\$9,940,581	Tier 2 Total	\$2,739,713	Tier 3 Total	\$4,413,219

hollis _ architect

Tier 1 - Option 4 = 40.7M

Blue Ridge	X	Safety / Security	Playground Turf	\$235,000	Cafeteria / Kitchen Improvements	\$393,750		
	X	Building Infrastructure	Exterior Tuckpointing	\$46,875			Outlets in Classroom	\$31,500
	X	Building Infrastructure	Roofs	\$53,458			Classroom Casework	\$301,219
	X	Building Infrastructure	Windows	\$131,040			*Façade Modernization	\$1,443,750
		Enhanced Learning Environ.	Interior Flooring Replacement(Corridor Only)	\$119,850				
		Enhanced Learning Environ.	Interior Door Replacement	\$94,500				
		Enhanced Learning Environ.	Lighting Upgrades	\$164,063				
		Building Infrastructure	Concrete & Asphalt Repairs	\$77,287				
		Enhanced Learning Environ.	Epoxy on Corridor Walls	\$137,813				
		Enhanced Learning Environ.	Gym Upgrades	\$50,000				
	X	Enhanced Learning Environ.	Media Center Upgrades (Carpet, Painting)	\$100,000				
	X	Safety / Security	Electronic Door Access	\$42,500				
		Enhanced Learning Environ.	Additional Freezer Space in Kitchen	\$25,000				



Tier 1 - Option 4 = 40.7M

			op					
	X	Safety / Security	Playground Turf	\$235,000	Car Rider Canopy	\$0	*Exterior Doors	\$45,675
Eastwood Hills		Building Infrastructure	Exterior Tuckpointing	\$0			Outlets in Classroom	\$28,362
		Building Infrastructure	Roofs	\$0				
		Building Infrastructure	Windows	\$58,800				
	X	Enhanced Learning Environ.	Interior Flooring Replacement(Corridor Only)	\$113,625				
	X	Enhanced Learning Environ.	Interior Door Replacement	\$94,500				
		Enhanced Learning Environ.	Lighting Upgrades	\$166,163				
	X	Building Infrastructure	Concrete & Asphalt Repairs	\$67,200				
		Enhanced Learning Environ.	Epoxy on Corridor Walls	\$0				
		Enhanced Learning Environ.	Gym Upgrades	\$50,000				
	X	Enhanced Learning Environ.	Media Center Upgrades (Carpet, Painting)	\$100,000				
		Enhanced Learning Environ.	Window Treatments	\$14,438				
	X	Safety / Security	Electronic Door Access	\$42,500				
				•				



Tier 1 - Option 4 = 40.7M

Fleetridge	X	Safety / Security	Playground Turf	\$235,000		Outlets in Classroom	\$35,000
		Building Infrastructure	Exterior Tuckpointing	\$0		Façade Modernization	\$1,187,500
		Building Infrastructure	Roofs (HALF)	\$275,625			
		Building Infrastructure	Windows	\$147,000			
	X	Enhanced Learning Environ.	Interior Flooring Replacement(Corridor Only)	\$93,645			
		Enhanced Learning Environ.	Interior Door Replacement	\$94,500			
		Enhanced Learning Environ.	Lighting Upgrades	\$24,150			
		Building Infrastructure	Concrete & Asphalt Repairs	\$68,841			
		Enhanced Learning Environ.	Epoxy on Corridor Walls	\$42,500			
	X	Enhanced Learning Environ.	Gym Upgrades	\$50,000			
		Enhanced Learning Environ.	Media Center Upgrades (Carpet, Painting)	\$100,000			
	X	Enhanced Learning Environ.	Student Restroom Addition	\$469,219			
		Enhanced Learning Environ.	Media Center Upgrades	\$295,313			
		Safety / Security	Electronic Door Access	\$42,500			
		Enhanced Learning Environ.	Additional Freezer Space in Kitchen	\$25,000			



Tier 1 - Option 4 = 40.7M

Laurel Hills	X	Safety / Security	Playground Turf	\$235,000	*Classroom Casework	\$265,625	*Cafeteria Improvements	\$997,500
		Building Infrastructure	Exterior Tuckpointing	\$0			*Façade Modernization	\$1,401,488
		Building Infrastructure	Roofs	\$11,813				
		Building Infrastructure	Windows	\$147,000				
	X	Enhanced Learning Environ.	Interior Flooring Replacement(Corridor Only)	\$93,645				
		Enhanced Learning Environ.	Interior Door Replacement	\$94,500				
		Enhanced Learning Environ.	Lighting Upgrades	\$146,475				
	X	Building Infrastructure	Concrete & Asphalt Repairs	\$161,700				
		Enhanced Learning Environ.	Epoxy on Corridor Walls	\$0				
		Enhanced Learning Environ.	Gym Upgrades	\$50,000				
		Enhanced Learning Environ.	Media Center Upgrades (Carpet, Painting)	\$100,000				
	X	Building Infrastructure	Main Electrical Panel Replacement	\$181,250				
		Safety / Security	Electronic Door Access	\$42,500				
•	X	Enhanced Learning Environ.	Student Restroom Addition	\$469,219				
						•		

hollis _ architect

Tier 1 - Option 4 = 40.7M

	X	Safety / Security	Playground Turf	\$235,000	*Car Rider Canopy	\$121,875	
Little Blue		Building Infrastructure	Exterior Tuckpointing	\$0			
		Building Infrastructure	Roof Repairs	\$25,000			
	X	Building Infrastructure	Windows	\$11,156			
	X	Enhanced Learning Environ.	Interior Flooring Replacement	\$82,500			
		Enhanced Learning Environ.	Interior Door Replacement	\$0			
	Х	Enhanced Learning Environ.	Lighting Upgrades	\$297,860			
	Х	Building Infrastructure	Concrete & Asphalt Repairs	\$65,625			
		Enhanced Learning Environ.	Epoxy on Corridor Walls	\$0			
		Enhanced Learning Environ.	Additional Playground Equipment	\$80,000			
	Х	Building Infrastructure	Retaining Wall Repairs	\$62,500			
·		Safety / Security	Electronic Door Access	\$42,500			



Raytown Facility Assessment

Tier 1 - Option 4 = 40.7M

			op					
	Х	Safety / Security	Playground Turf	\$235,000	*Car Rider Canopy	\$121,875		
Norfleet		Building Infrastructure	Exterior Tuckpointing	\$0			Outlets in Classroom	
	X	Building Infrastructure	Roofs (HALF)	\$248,259				
		Building Infrastructure	Windows	\$11,156				
	X	Enhanced Learning Environ.	Interior Flooring Replacement(Corridor Only)	\$133,875				
		Enhanced Learning Environ.	Interior Door Replacement	\$42,000				
		Enhanced Learning Environ.	Lighting Upgrades	\$58,800				
		Building Infrastructure	Concrete & Asphalt Repairs	\$108,780				
	X	Enhanced Learning Environ.	Epoxy on Corridor Walls	\$124,130			Façade Modernization	\$1,576,250
	X	Enhanced Learning Environ.	Gym Upgrades	\$50,000				
	X	Enhanced Learning Environ.	Media Center Upgrades (Carpet, Painting)	\$100,000				
		Enhanced Learning Environ.	Epoxy on Corridor Walls	\$195,000				
	Х	Safety / Security	Electronic Door Access	\$42,500				
		Enhanced Learning Environ.	Additional Freezer Space in Kitchen	\$25,000				



Tier 1 - Option 4 = 40.7M

	X	Safety / Security	Playground Turf	\$235,000	*Cafeteria Improvements	\$525,000	Façade Modernization	\$1,440,000
Robinson		Building Infrastructure	Exterior Tuckpointing	\$52,500			Outlets in Classroom	\$35,000
		Building Infrastructure	Roofs	\$0				
		Building Infrastructure	Windows	\$11,156				
	X	Enhanced Learning Environ.	Interior Flooring Replacemen(Corridor Only)	\$88,315				
		Enhanced Learning Environ.	Interior Door Replacement	\$52,500				
		Enhanced Learning Environ.	Lighting Upgrades	\$173,250				
		Building Infrastructure	Concrete & Asphalt Repairs	\$147,000				
	X	Enhanced Learning Environ.	Epoxy on Corridor Walls	\$113,400				
	X	Enhanced Learning Environ.	Gym Upgrades	\$50,000				
	X	Enhanced Learning Environ.	Media Center Upgrades (Carpet, Painting)	\$100,000				
	X	Enhanced Learning Environ.	Renovation of two lower level classrooms	\$236,250				
The state of the s	X	Safety / Security	Electronic Door Access	\$42,500				



Tier 1 - Option 4 = 40.7M

			op					
	X	Safety / Security	Playground Turf	\$235,000	Stair Access to Lower Lot	\$32,000	Interior Door Replacement	\$57,750
Southwood		Building Infrastructure	Exterior Tuckpointing	\$65,625	*Courtyard Upgrades	\$535,000		
		Building Infrastructure	Roofs	\$104,213			*Front Office Renovation	\$236,250
		Building Infrastructure	Windows	\$11,156			*Cafeteria Improvements	\$787,500
	X	Enhanced Learning Environ.	Interior Flooring Replacemen(Corridor Only)	\$88,315				
		Enhanced Learning Environ.	Interior Door Replacement	\$42,000				
	X	Enhanced Learning Environ.	Lighting Upgrades	\$162,225				
	X	Building Infrastructure	Concrete & Asphalt Repairs	\$381,500				
		Enhanced Learning Environ.	Epoxy on Corridor Walls	\$105,722				
		Enhanced Learning Environ.	Gym Upgrades	\$50,000				
	X	Enhanced Learning Environ.	Media Center Upgrades (Carpet, Painting)	\$100,000				
		Enhanced Learning Environ.	Furniture	\$531,250				
	X	Safety / Security	Electronic Door Access	\$44,625				



Tier 1 - Option 4 = 40.7M

Spring Valley	X	Safety / Security	Playground Turf	\$235,000	Car Rider Canopy	\$170,625	
		Building Infrastructure	Exterior Tuckpointing	\$0	Courtyard Improvements	\$118,125	
		Building Infrastructure	Roofs	\$55,125			
		Building Infrastructure	Windows	\$11,156			
	X	Enhanced Learning Environ.	Interior Flooring Replacemen(Corridor Only)	\$133,875			
		Enhanced Learning Environ.	Interior Door Replacement	\$42,000			
		Enhanced Learning Environ.	Lighting Upgrades	\$51,975			
	X	Building Infrastructure	Concrete & Asphalt Repairs	\$92,400			
	X	Enhanced Learning Environ.	Epoxy on Corridor Walls	\$0			
	X	Enhanced Learning Environ.	Gym Upgrades	\$50,000			
	X	Enhanced Learning Environ.	Media Center Upgrades (Carpet, Painting)	\$100,000			
		Enhanced Learning Environ.	Furniture	\$562,500			
	X	Safety / Security	Electronic Door Access	\$44,625			
		Enhanced Learning Environ.	Additional Freezer Space in Kitchen	\$25,000			



Tier 1 - Option 4 = 40.7M

Westridge	X	Safety / Security	Playground Turf	\$235,000	Courtyard Upgrade	\$433,125	Façade Modernization	\$1,241,888
		Building Infrastructure	Exterior Tuckpointing	\$65,625				
		Building Infrastructure	Roofs	\$0				
		Building Infrastructure	Windows	\$52,500				
	X	Enhanced Learning Environ.	Interior Flooring Replacemen(Corridor Only)	\$129,855				
		Enhanced Learning Environ.	Interior Door Replacement	\$52,500				
		Enhanced Learning Environ.	Lighting Upgrades	\$169,575				
	X	Building Infrastructure	Concrete & Asphalt Repairs	\$264,600				
	X	Enhanced Learning Environ.	Epoxy on Corridor Walls	\$137,813				
	X	Enhanced Learning Environ.	Gym Upgrades	\$50,000				
	X	Enhanced Learning Environ.	Media Center Upgrades (Carpet, Painting)	\$100,000				
	X	Building Infrastructure	Additional Parking	\$225,000				
	X	Enhanced Learning Environ.	Epoxy on Corridor Walls	\$137,813				
	X	Safety / Security	Electronic Door Access	\$44,625				



Tier 1 - Option 4 = 40.7M

	X	Safety / Security	Playground Shade Structure	\$20,000	Front Office Renovation	\$236,250	Multi-purpose Room Addition	\$1,750,000
New Trails	X	Safety / Security	Playground Turf	\$210,984				
	X	Building Infrastructure	Roof Restoration	\$236,250				
	X	Building Infrastructure	Breezeway Repairs	\$105,000				

hollis _ architect

Tier 1 - Option 4 = 40.7M

	X	Building Infrastructure	HVAC - Boiler Upgrade	\$459,375	Courtyard Updates	\$577,500		
Three Trails	X	Building Infrastructure	Roofs	\$826,875				
	X	Building Infrastructure	Window Replacement	\$183,750				
	X	Building Infrastructure	Tuckpointing	\$387,188				
	X	Enhanced Learning Environ.	Playground Equipment	\$50,000				
	X	Enhanced Learning Environ.	Window Treatments	\$14,348				
	X	Building Infrastructure	Concrete & Asphalt Repairs	\$202,125				
		Safety / Security	PA / Intercom	\$40,000				
			Tier 1 Total	\$17,220,602	Tier 2 Total	\$3,530,750	Tier 3 Total	\$12,596,631



Tier 1 - Option 4 = 40.7M

Northwood	Х	Enhanced Learning Environ.	Lighting Upgrades	\$67,200		
	Х	Enhanced Learning Environ.	ADA Playground Equipment	\$150,000		
	Х	Enhanced Learning Environ.	Interior Doors Repalcement	\$21,000		
	Х	Building Infrastructure	Outlets in ClaSafety / Securitysrooms	\$33,600		
	Х	Building Infrastructure	Roof Improvements	\$195,000		
	X	Enhanced Learning Environ.	Expand Life Skills Room	\$172,266		
			Tier 1 Total	\$639,066		



Tier 1 - Option 4 = 40.7M

Herndon Campus								
Building A	Χ	Enhanced Learning Environ.	Cosmatology Flooring (Concrete)	\$22,148	New Restaurant (Building D)	\$3,300,000	Diesel Classroom Space	\$75,000
Building B	Χ	Building Infrastructure	Roofs - Building B	\$393,750	Canopy System Between Buildings	\$900,000		
Building C	Χ	Enhanced Learning Environ.	Culinary Space Improvements	\$125,000				
	Χ	Enhanced Learning Environ.	Nursing Shower	\$15,500				
				\$556,398		\$4,200,000		\$75,000



0.22.2018 Tier 1 - Option 4 = 40.7M

		Ticl 2 Option 4 = 40771							
Raytown Success Academy									
OVERALL TOTALS		Tier 1 Total	\$40,744,822	Tier 2 Total	\$18,373,025	Tier 3 Total	\$26,759,362		



Next Meeting:

November 26, 2018

Review LRP and Exploring Bond Options

Thank you!!

hollis __ architect