

PROPOSAL

Bid ID Number:47012 Date:6/7/2021

1225 Iron - North Kansas City, Missouri 64116 - Office (816) 842-6066 - Fax (816) 842-1638

Bid Submitted To:

Raytown School District 5911Blue Ridge Blvd. Raytown, MO 64133

PHONE: 8162687160

CONTACT: Josh Hustad

Job Proposed:

Raytown High School Track 6019 Blue Ridge Blvd Raytown, MO 64133

TIPS Cooperative Purchasing Contract Number: 20020501

DescriptionQuantityUnitsNet PriceTrack Resurfacing4,825\$195,000.00

Track Surface Removal:

- Use skid steers and scrapers to remove existing track surface and haul offsite
- Clean existing asphalt base free of debris
- *** ASPHALT NOTE: Once track surface has been removed, an asphalt inspection/site walk shall take place with a representative from the school district and a representative from MAC to inspect the condition of the asphalt and determine a plan to repair the asphalt prior to new track surface installation.

FAX:

Track Surface:

- Supply and install a permeable 13mm Polyurethane Basemat and two coats of structural spray track surface.
- Layout and stripe running track
- Track Color to be RED or BLACK

Contingenc

- Allowance for asphalt repairs based on inspection once old track surface has been remove

\$30,000.00

Based on tax exempt prices.

A Project Exemption Certificate must be furnished before the start of work.

EXCLUSIONS:

- *Bonds, Permits and Testing.
- *Repairing high or low spots unless stated above.
- *Correcting planarity unless stated above.
- *Pressure washing unless stated above.
- *Asphalt or concrete work unless stated above.
- *Seeding or sodding.
- *Any items not listed above.

Total \$225,000.00

Add \$194,500.00

Add Alternate: Remove and Replace Asphalt

- Use Milling machine to remove asphalt full depth
- Lasergrade subgrade
- Pave 3" of asphalt base and roll to compaction
- Pave 2" of asphiat surface and roll to compaction



PROPOSAL

Bid ID Number:47072 Date:6/7/2021

1225 Iron - North Kansas City, Missouri 64116 - Office (816) 842-6066 - Fax (816) 842-1638

Bid Submitted To:

Raytown Quality Schools 5911 Blue Ridge Blvd. Raytown, MO 64133

PHONE: (816) 268-7160

FAX:

CONTACT: Josh Hustad

Job Proposed:

Raytown South High School Track 8211 Sterling Ave Raytown, MO 64138

TIPS Cooperative Purchasing Contract Number: 20020501

Net Price Quantity Units Description

6,400 \$250,000.00 Track Resurfacing

Track Surface Removal:

- Use skid steers and scrapers to remove existing track surface and haul offsite - Clean existing asphalt base free of debris

*** ASPHALT NOTE: Once track surface has been removed, an asphalt inspection/site walk shall take place with a representative from the school district and a representative from MAC to inspect the condition of the asphalt and determine a plan to repair the asphalt prior to new track surface installation.

Track Surface:

- Supply and install a permeable 13mm Polyurethane Basemat and two coats of structural spray track surface.
- Layout and stripe running track
- Track Color to be RED or BLACK

Contingency - Allowance for asphalt repairs based on inspection once old track surface has been remove

EXCLUSIONS:

- *Bonds, Permits and Testing.
- *Repairing high or low spots unless stated above.
- *Correcting planarity unless stated above.
- *Pressure washing unless stated above.
- *Asphalt or concrete work unless stated above.
- *Seeding or sodding.
- *Any items not listed above.

\$280,000.00 **Total**

\$30,000.00

Initials



PROPOSAL

Bid ID Number:48549 Date:6/29/2021

1225 Iron - North Kansas City, Missouri 64116 - Office (816) 842-6066 - Fax (816) 842-1638

FAX:

Bid Submitted To:

Raytown School District 5911 Blue Ridge Blvd. Raytown, MO 64133

PHONE: 8162687160

CONTACT: Josh Hustad

Job Proposed:

Raytown Middle School Tracks 4900 Pittman Rd

Kansas City, MO 64113

TIPS Cooperative Purchasing Contract Number: 20020501

Description Quantity Units Net Price

Long Term - Asphalt Replacement

Asphalt Milling:

Use milling machines to remove asphalt full depth and haul off site

Supgrade Prep:

Lasregrade subgrade as needed

- 500 tons of rock included if needed.

Repair Broken Curb

Remove and replace 100 Lineal Feet of Broken Curb as needed.

Asphalt Paving:

Pave three (3) inches of base asphalt and roll to compaction Pave two (2) inches of surface asphalt and roll to compaction

Track Striping:

Layout and Stripe Running Track

Raytown Middle School

\$290,000.00

Raytown South Middle School

\$290,000.00

Add Alternate: Add Track Surfacing

- Supply and Install a 1/2" Polyurethane basemat with structural spray wearing course Track surface over new asphalt pavement.

5,000 SY

\$200,000.00 Per Track